



Magnetic Disturbance of as much as 7° exist at sea level in this vicinity

Magnetic Disturbance of as much as 5° exist at sea level in this vicinity

WARNING
DUE TO PROXIMITY OF THE MAGNETIC POLE THE MAGNETIC COMPASS MAY BE UNRELIABLE FOR NAVIGATION BECAUSE OF MAGNETIC AND WEAK DIRECTIVE FORCE.

MAXIMUM LIMIT OF PACK ICE SUBJECT TO WIDE UNPREDICTABLE SEASONAL AND ANNUAL CHANGE